


How to trim a flying bias



How to Quicktrim™ your Waterbird® Parasail

During your parasails useful working life it may begin to fly predominantly to one side, this is called a Bias.

Any Bias that develops can be easily corrected by the use of the Quicktrim™ zips fitted to all Waterbird® parasails.

Before commencing of trimming ensure that both Trim zips are fully open

To correct a parasail that flies predominantly to the Left close the Right Trim Zip by approximately 3cm.

Test fly the parasail

If the parasail still flies to the Left side repeat the operation closing the right zip a further 3cm.

Test fly the parasail

Repeat this procedure until straight flight is achieved.

When the operation is completed ensure that the self locking zip puller is pressed firmly into place.

To correct a parasail that flies predominantly to the Right close the Left Trim Zip by approximately 3cm.

Test fly the parasail

If the parasail still flies to the Right side repeat the operation by closing the Left zip a further 3cm. Test fly the parasail.

Repeat this procedure until straight flight is achieved.

When the operation is completed ensure that the self locking zip puller is pressed firmly into place.

A bias that cannot be corrected using the Quicktrim™ system is outside the range of normal adjustment and requires professional attention.

NOTE: All parasails over 36ft have double "Quicktrim" zips on each side of the canopy.

Warning: Do not adjust or shorten any of the 16 lines of the canopy to correct a bias.

Tel. 00 44 (0) 1474 853675 Fax. 00 44 (0) 1474 854474

Email: Info@waterbird.co.uk